

## **5.0 APPENDIX A**

Figure 1. Existing conditions near location for main rock drop.

Figure 2. Installation of main rock drop and pond inlet channel.

Figure 3. Plan view of main rock drop.

Figure 4. Oblique aerial view showing main rock drop and vicinity.

Figure 5. Location of Hanson Ponds rock drops.

Figure 6. Location of rock drops in the egress channel of Hanson Ponds.

Figure 7. Map of Wetlands One and Two.

Table 1. Summary table for main rock drop and sewer line vicinity.




Figure 1. Existing conditions near location for main rock drop (Entrix, Inc., 2003).




Figure 2. Installation of main rock drop and pond inlet channel (Entrix, Inc., 2003).




Figure 3. Plan view of main rock drop (Entrix, Inc., 2003)




Figure 4. Oblique aerial view showing main rock drop and vicinity (Entrix, Inc., 2003)




Figure 5. Location of Hanson Ponds rock drops (Entrix, Inc., 2003).




Figure 6. Location of rock drops in the egress channel of Hanson Ponds (Entrix, Inc., 2003).






Figure 7. Map of Wetlands One and Two (Sheldon and Associates, Inc., 2003).



